Cloud Service Hub Supported Models

Direct Connection (Via Multi Function Printer Panel)

Item	Description
Colour	Apeos C2060 *1 *5 Apeos C2061 *1 *5 Apeos C2560 *1 *5 Apeos C2561 *1 *5 Apeos C2567 *1 *5 Apeos C3060 *1 *5 Apeos C3061 *1 *5 Apeos C3067 *1 *5 Apeos C3070 *1 *5 Apeos C3071 *1 *5 Apeos C3072 *1 *5 Apeos C3530 *1 *5 Apeos C3567 *1 *5 Apeos C3570 *1 *5 Apeos C3571 *1 *5 Apeos C3572 *1 *5 Apeos C4030 *1 *5 Apeos C4570 *1 *5 Apeos C4571 *1 *5 Apeos C4572 *1 *5 Apeos C5240 *1 *5 Apeos C5570 *1 *5 Apeos C5571 *1 *5 Apeos C5572 *1 *5 Apeos C6570 *1 *5 Apeos C6571 *1 *5 Apeos C6572 *1 *5 Apeos C6580 *1 *5 Apeos C7070 *1 *5 Apeos C7071 *1 *5 Apeos C7072 *1 *5 Apeos C7580 *1 *5 Apeos C8180 *1 *5 ApeosPort C2060 *1 *5 ApeosPort C2560 *1 *5 ApeosPort C3060 *1 *5 ApeosPort C3070 *1 *5 ApeosPort C3570 *1 *5 ApeosPort C4570 *1 *5 ApeosPort C5570 *1 *5 ApeosPort C6570 *1 *5

Item	Description
	ApeosPort C7070 *1 *5 ApeosPort-V C2276 *2 ApeosPort-V C3320 *3 ApeosPort-V C3374 *2 ApeosPort-V C3376 *2 ApeosPort-V C4476 *2 ApeosPort-V C5576 *2 ApeosPort-V C5585 *4 ApeosPort-V C6676 *2 ApeosPort-V C6685 *4 ApeosPort-V C7776 *2 ApeosPort-V C7785 *4 ApeosPort-VI C2271 *5 ApeosPort-VI C3370 *5 ApeosPort-VI C3371 *5 ApeosPort-VI C4471 *5 ApeosPort-VI C5571 *5 ApeosPort-VI C6671 *5 ApeosPort-VI C7771 *5 ApeosPort-VII C2273 *1 *5 ApeosPort-VII C3321 *1 *5 ApeosPort-VII C3372 *1 *5 ApeosPort-VII C3373 *1 *5 ApeosPort-VII C4421 *1 *5 ApeosPort-VII C4473 *1 *5 ApeosPort-VII C5573 *1 *5 ApeosPort-VII C5588 *1 *5 ApeosPort-VII C6673 *1 *5 ApeosPort-VII C6688 *1 *5 ApeosPort-VII C7773 *1 *5 ApeosPort-VII C7788 *1 *5 ApeosPro C650 *1 *5 ApeosPro C750 *1 *5 ApeosPro C810 *1 *5 DocuCentre SC2022 *5 *6 (Support ended in June 2026) DocuCentre-V C2263 *7 *8 DocuCentre-V C2265 *7 *8 DocuCentre-V C2276 *2 DocuCentre-V C3374 *2 DocuCentre-V C3376 *2 DocuCentre-V C4476 *2 DocuCentre-V C5576 *2 DocuCentre-V C5585 *4 DocuCentre-V C6676 *2 DocuCentre-V C6685 *4

Item	Description
	DocuCentre-V C7776 *2 DocuCentre-V C7785 *4 DocuCentre-VI C2271 *5 DocuCentre-VI C3370 *5 DocuCentre-VI C3371 *5 DocuCentre-VI C4471 *5 DocuCentre-VI C5571 *5 DocuCentre-VI C6671 *5 DocuCentre-VI C7771 *5 DocuCentre-VII C2273 *1 *5 DocuCentre-VII C3372 *1 *5 DocuCentre-VII C3373 *1 *5 DocuCentre-VII C4473 *1 *5 DocuCentre-VII C5573 *1 *5 DocuCentre-VII C5588 *1 *5 DocuCentre-VII C6673 *1 *5 DocuCentre-VII C6688 *1 *5 DocuCentre-VII C7773 *1 *5 DocuCentre-VII C7788 *1 *5 DocuPrint CM315 z *5 *6 (Support ended in June 2026) DocuPrint CM318 z *5 *6 (Support ended in June 2026) DocuPrint CM415 AP *3
B/W	Apeos 2560 *1 *5 Apeos 2561 *1 *5 Apeos 3060 *1 *5 Apeos 3061 *1 *5 Apeos 3560 *1 *5 Apeos 3561 *1 *5 Apeos 4570 *1 *5 Apeos 4830 *1 *5 Apeos 5330 *1 *5 Apeos 5570 *1 *5 Apeos 6340 *1 *5 Apeos 6580 *1 *5 Apeos 7580 *1 *5 ApeosPort 2560 *1 *5 ApeosPort 3060 *1 *5 ApeosPort 3560 *1 *5 ApeosPort 4570 *1 *5 ApeosPort 5570 *1 *5 ApeosPort-V 2060 *9 ApeosPort-V 3060 *9 ApeosPort-V 3065 *9 ApeosPort-V 4020 *3

Item	Description
	ApeosPort-V 4070 *10 ApeosPort-V 5070 *10 ApeosPort-V 6080 *11 ApeosPort-V 7080 *11 ApeosPort-VII 4021 *1 *5 ApeosPort-VII 5021 *1 *5 DocuCentre-V 2060 *8 *9 *12 DocuCentre-V 3060 *8 *9 *12 DocuCentre-V 3065 *8 *9 *12 DocuCentre-V 4070 *10 DocuCentre-V 5070 *10 DocuCentre-V 6080 *11 DocuCentre-V 7080 *11 DocuPrint M465 AP

Note: Products for sale may differ according to country or region. For more information, please contact the FUJIFILM Business Innovation office or authorized dealers in each country/region.

Note: Cloud Service Hub Client App must be installed.

*1: You can log in with Microsoft Entra ID user account.

*2: Cloud Service Hub Client App is pre-installed on the device if the version of Controller Software is 1.1.15 or higher.

*3: Cloud Service Hub Client App is pre-installed on the device if the version of Controller Software is 1.2.7 or higher.

*4: The controller software should be version 1.2.14 or higher. Cloud Service Hub Client App is pre-installed on the device.

*5: Cloud Service Hub Client App is pre-installed on the device.

*6: Finisher support on printing, OCR / Skip Blank Pages / Auto Upright Orientation / Skew Correction on scanning, storage of DocuWorks files or high-compressed PDF, print of DocuWorks files, print restriction, and notification on the device control panel are not supported.

*7: Cloud Service Hub Client App is pre-installed on the device if the version of Controller Software is 1.0.30 or higher.

*8: Needs to be equipped with HDD Extension Kit.

*9: Cloud Service Hub Client App is pre-installed on the device if the version of Controller Software is 1.0.31 or higher.

*10: The controller software needs to be updated to version 1.0.15 or higher. Cloud Service Hub Client App is pre-installed on the device.

*11: The controller software needs to be updated to version 1.0.14 or higher. Cloud Service Hub Client App is pre-installed on the device.

*12: Needs to be equipped with Printer Kit.

Fuji Xerox has changed its name to FUJIFILM Business Innovation as of April1, 2021. FUJIFILM Business Innovation continues to provide maintenance services with respect to products sold under the Xerox and Fuji Xerox brands.
Xerox, Xerox and Design, as well as Fuji Xerox, Fuji Xerox and Design are registered trademarks or trademarks of Xerox Corporation in Japan and/or other countries.