

Direct Connection (Via Multi Function Printer Panel)

Item	Description
Colour	Apeos C2060 *1 *5
	Apeos C2061 *1 *5
	Apeos C2560 *1 *5
	Apeos C2561 *1 *5
	Apeos C2567 *1 *5
	Apeos C3060 *1 *5
	Apeos C3061 *1 *5
	Apeos C3067 *1 *5
	Apeos C3070 *1 *5
	Apeos C3071 *1 *5
	Apeos C3530 *1 *5
	Apeos C3567 *1 *5
	Apeos C3570 *1 *5
	Apeos C3571 *1 *5
	Apeos C4030 *1 *5
	Apeos C4570 *1 *5
	Apeos C4571 *1 *5
	Apeos C5240 *1 *5
	Apeos C5570 *1 *5
	Apeos C5571 *1 *5
	Apeos C6570 *1 *5
	Apeos C6571 *1 *5
	Apeos C6580 *1 *5
	Apeos C7070 *1 *5
	Apeos C7071 *1 *5
	Apeos C7580 *1 *5
	Apeos C8180 *1 *5
	ApeosPort C2060 *1 *5
	ApeosPort C2560 *1 *5
	ApeosPort C3060 *1 *5
	ApeosPort C3070 *1 *5
	ApeosPort C3570 *1 *5
	ApeosPort C4570 *1 *5
	ApeosPort C5570 *1 *5
	ApeosPort C6570 *1 *5
	ApeosPort C7070 *1 *5
	ApeosPort-V C2276 *2
	ApeosPort-V C3320 *3
	ApeosPort-V C3374 *2
	ApeosPort-V C3376 *2
	ApeosPort-V C4476 *2

Item	Description
	ApeosPort-V C5576 *2
	ApeosPort-V C5585 *4
	ApeosPort-V C6676 *2
	ApeosPort-V C6685 *4
	ApeosPort-V C7776 *2
	ApeosPort-V C7785 *4
	ApeosPort-VI C2271 *5
	ApeosPort-VI C3370 *5
	ApeosPort-VI C3371 *5
	ApeosPort-VI C4471 *5
	ApeosPort-VI C5571 *5
	ApeosPort-VI C6671 *5
	ApeosPort-VI C7771 *5
	ApeosPort-VII C2273 *1 *5
	ApeosPort-VII C3321 *1 *5
	ApeosPort-VII C3372 *1 *5
	ApeosPort-VII C3373 *1 *5
	ApeosPort-VII C4421 *1 *5
	ApeosPort-VII C4473 *1 *5
	ApeosPort-VII C5573 *1 *5
	ApeosPort-VII C5588 *1 *5
	ApeosPort-VII C6673 *1 *5
	ApeosPort-VII C6688 *1 *5
	ApeosPort-VII C7773 *1 *5
	ApeosPort-VII C7788 *1 *5
	ApeosPro C650 *1 *5
	ApeosPro C750 *1 *5
	ApeosPro C810 *1 *5
	DocuCentre SC2022 *5 *6
	DocuCentre-V C2263 *7 *8
	DocuCentre-V C2265 *7 *8
	DocuCentre-V C2276 *2
	DocuCentre-V C3374 *2
	DocuCentre-V C3376 *2
	DocuCentre-V C4476 *2
	DocuCentre-V C5576 *2
	DocuCentre-V C5585 *4
	DocuCentre-V C6676 *2
	DocuCentre-V C6685 *4
	DocuCentre-V C7776 *2
	DocuCentre-V C7785 *4
	DocuCentre-VI C2271 *5
	DocuCentre-VI C3370 *5
	DocuCentre-VI C3371 *5

Item	Description
	DocuCentre-VI C4471 *5 DocuCentre-VI C5571 *5 DocuCentre-VI C6671 *5 DocuCentre-VI C7771 *5 DocuCentre-VII C2273 *1 *5 DocuCentre-VII C3372 *1 *5 DocuCentre-VII C3373 *1 *5 DocuCentre-VII C4473 *1 *5 DocuCentre-VII C5573 *1 *5 DocuCentre-VII C5588 *1 *5 DocuCentre-VII C6673 *1 *5 DocuCentre-VII C6688 *1 *5 DocuCentre-VII C7773 *1 *5 DocuCentre-VII C7788 *1 *5 DocuPrint CM315 z *5 *6 DocuPrint CM318 z *5 *6 DocuPrint CM415 AP *3
B/W	Apeos 2560 *1 *5 Apeos 2561 *1 *5 Apeos 3060 *1 *5 Apeos 3061 *1 *5 Apeos 3560 *1 *5 Apeos 3561 *1 *5 Apeos 4570 *1 *5 Apeos 4830 *1 *5 Apeos 5330 *1 *5 Apeos 5570 *1 *5 Apeos 6340 *1 *5 Apeos 6580 *1 *5 Apeos 7580 *1 *5 ApeosPort 2560 *1 *5 ApeosPort 3060 *1 *5 ApeosPort 3560 *1 *5 ApeosPort 4570 *1 *5 ApeosPort 5570 *1 *5 ApeosPort-V 2060 *9 ApeosPort-V 3060 *9 ApeosPort-V 3065 *9 ApeosPort-V 4020 *3 ApeosPort-V 4070 *10 ApeosPort-V 5070 *10 ApeosPort-V 6080 *11 ApeosPort-V 7080 *11 ApeosPort-VII 4021 *1 *5

Item	Description
	ApeosPort-VII 5021 *1 *5
	DocuCentre-V 2060 *8 *9 *12
	DocuCentre-V 3060 *8 *9 *12
	DocuCentre-V 3065 *8 *9 *12
	DocuCentre-V 4070 *10
	DocuCentre-V 5070 *10
	DocuCentre-V 6080 *11
	DocuCentre-V 7080 *11
	DocuPrint M465 AP

Note: Products for sale may differ according to country or region. For more information, please contact the FUJIFILM Business Innovation office or authorized dealers in each country/region.

Note: Cloud Service Hub Client App must be installed.

- *1: You can log in with Microsoft Entra ID user account.
- *2: Cloud Service Hub Client App is pre-installed on the device if the version of Controller Software is 1.1.15 or higher.
- *3: Cloud Service Hub Client App is pre-installed on the device if the version of Controller Software is 1.2.7 or higher.
- *4: The controller software should be version 1.2.14 or higher. Cloud Service Hub Client App is pre-installed on the device.
- *5: Cloud Service Hub Client App is pre-installed on the device.
- *6: Finisher support on printing, OCR / Skip Blank Pages / Auto Upright Orientation / Skew Correction on scanning, storage of DocuWorks files or high-compressed PDF, print of DocuWorks files, print restriction, and notification on the device control panel are not supported.
- *7: Cloud Service Hub Client App is pre-installed on the device if the version of Controller Software is 1.0.30 or higher.
- *8: Needs to be equipped with HDD Extension Kit.
- *9: Cloud Service Hub Client App is pre-installed on the device if the version of Controller Software is 1.0.31 or higher.
- *10: The controller software needs to be updated to version 1.0.15 or higher. Cloud Service Hub Client App is pre-installed on the device.
- *11: The controller software needs to be updated to version 1.0.14 or higher. Cloud Service Hub Client App is pre-installed on the device.
- *12: Needs to be equipped with Printer Kit.

Fuji Xerox ได้เปลี่ยนชื่อบริษัทเป็น FUJIFILM Business Innovation เมื่อวันที่ 1 เมษายน 2021 โดย FUJIFILM Business Innovation จะยังคงให้บริการการบำรุงรักษาสำหรับผลิตภัณฑ์ที่ได้อำนาจภายใต้แบรนด์ Xerox และ Fuji Xerox ต่อไป
Xerox, Xerox และโลโก รวมถึง Fuji Xerox, Fuji Xerox และโลโก เป็นเครื่องหมายการค้าจดทะเบียนหรือเครื่องหมายการค้าของ Xerox Corporation ในประเทศญี่ปุ่นและ/หรือประเทศอื่นๆ